

### I32 and PRE32 Molex Connector for MM30 Installation Notice

Topic: Molex connector no longer installed in I32 and PRE32 shipped without MM30.

Molex ceased production of the connector used to install the MM30 in I32 and PRE32 over two years ago. At that time we believed that we had sufficient stock to last the full lifespan of those models.

However, recent inventory analysis has indicated the possibility of needing more connectors than originally forecast. We have been unable to source any additional connectors, so have begun shipping I32 and PRE32 models without the Molex connector in order to maintain a sufficient inventory to satisfy expected worldwide demand.

As a result, when considering the installation of an MM30 board, please confirm whether or not the Molex connector is required for the specific I32 or PRE32 in to which the media module is to be installed from the serial number list below and order accordingly.

<u>I32</u>	<u>PRE32</u>	
1132-6000 and forward	3232-6000 and forward	3232-5170
1132-5043	3232-140	3232-5190
1132-5061	3232-5127	3232-5196
1132-5165	3232-5139	3232-5198
1132-5209	3232-5144	3232-5203
1132-5241	3232-5152	3232-5206
1132-5244	3232-5153	3232-5218
1132-5245	3232-5155	3232-5228
1132-5250	3232-5158	3232-5229
	3232-5159	3232-5232
	3232-5162	3232-5238
	3232-5166	3232-5241
	3232-5169	

For Molex connector and MM30 installation instructions and firmware see the documents available at this link: <http://www.primare.net/default.asp?ContentID=137>

